Annexure D

BUILDING SAFETY CERTIFICATE

No. 1072			Dated: 28/07/2025					
It is certified that the	existing but	ilding Sunb	eam Scho	ol, Sulta	news(nam	ne of the		
building or premises) at			•	r details below	Service of the servic	228118)		
Detail of Block(s) in	Block	Block	Block	Block	Block	Block		
school	(1)	(2)	(2)	40				

school	(1)	(2)	(3)	(4)	′ (5)	(6)
No. of Floor(s) in the Block	G+3		/	/		
The building is owned/of the Institution) have			safety requirer		rdance with N	AN I MADE TO STATE OF THE STATE

1. Building is constructed by school management in guidance of Nr. Anil

2. Tonden, Architect hence they are responsible for shuctural safety.

2. Building needs to be examined and maintained at regular interval,

1. hence it is responsibility of school management to take care of it. Issued on ... 28.1.0.71.2025... at .Vikas: B. havan; Sultanpur.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :_

Name : Alexander Fang

Designation ग्रामीण भी

Name & Address of Department/ Office: RED

Vikas Bhavan, Seltan pur